DESCRIPTION: VALVE TESTING P-26A (SEE COMMENTS BELOW)

SEU

WORKORDER

WORK ORDER #: 6136412

PMNUM:

PARENT WO #:

TARGET START DATE:

037-21362

TARGET COMP DATE: 5/5/2016

SCHEDULE START:

SCHEDULE FINISH:

ROUTE NUMBER:

STATUS: INPRG

REQUESTED BY: DMAINE

**REPORT DATE: 5/3/2016** 

PM ACTIVITY CLASS:

ASSET #: 24846

ASSET DESCRIPTION: GROUP 3 WELLS

LOCATION ID: AC-GROUP 3 WELLS

LOC. DESCRIPTION: PORTER 24, 26, 69, SITES, 34,35,42,43,44,46

PHYSICAL LOCATION:

RESPONSIBLE SUPERVISOR / OWNER

**WORK TYPE** 

PRIORITY

**ACCOUNT INFO** 

832,020

FIELD MAINT /

CM

2

4-6-16

REMARKS: PERFORMED FUNCTION TEST LISTED THE VALUES BELDW

Date Completed

DMAINE

Completed By

SAFETY CHECKLIST COMPLETED?

Estimated Labor Hours

Labor Code/Craft

ᆫ

Quantity

Planned Hours

Actual Hours

0

3-9-16

ON

150

COMMENTS:

4-6-16

,25

PERFORM FUNCTION TEST ON THE MASTER VALVE, TUBING WING VALVE, CASING WING VALVE, TUBING KILL WING VALVE AND THE CASING KILL WING VALVE.

LOCATION METERS:

LOG: